



ATC-70 #1

4/23/73

SERVICE BULLETIN

AMERICAN HONDA MOTOR CO., INC.

MOTORCYCLE SERVICE DEPARTMENT

OWNER'S MANUAL AND CHOKE LABEL

The first 5,500 ATC-70s were shipped without owner's manuals and with no choke instruction labels on the air cleaner covers.

Owner's manuals and choke instruction labels will be sent to all dealers who are invoiced for affected units. If you do not receive the correct number of owner's manuals or choke labels, contact the Field Service Section of the Motorcycle Service Department.

INSTALLATION PROCEDURE FOR CHOKE INSTRUCTION LABEL:

1. Clean the surface of the left air cleaner cover to remove all oil and dirt.
2. Peel the paper backing from the choke label, and center the label between the forward edge of the cover and the cover attaching nut.



AMERICAN HONDA MOTOR CO., INC.
MOTORCYCLE SERVICE DEPARTMENT

©American Honda Motor Co., Inc. 1973

ROUTING:

COPY 1
COPY 2

GENERAL MANAGER
 SERVICE MANAGER

SALES DEPT
 MECHANICS

OFFICE FILE
 SHOP FILE